Name of Policy:	Line Isolation Monitor Alarms	
Policy Number:	3364-124-24	THE UNIVERSITY OF TOLEDO MEDICAL CENTER
Department:	Nursing Service/Operating Room	
Approving Officer:	Director, Surgical Services	
Responsible Agent:	Chief Nursing Officer/CNO	Effective Date: 12/31/2022
Scope:	Operating Room/Perioperative Services	Initial Effective Date: 6/1993
		l revision of existing policy of existing policy

(A) Policy Statement

Operating Room (OR) staff will respond appropriately to activation of Line Isolation Monitor (LIM) alarms.

(B) Purpose of Policy

To assure safety of patients and staff from potential injury due to leaking electrical current.

(C) Procedure

- 1. OR staff will inspect all electrical equipment for damage prior to use. Damaged equipment will be handled as per Policy 3364-124-07.
- 2. In the event the Line Isolation Monitor (LIM) alarm is activated, the RN circulator will:
 - a. systematically unplug all pieces of electrical equipment plugged into the alarming LIM until the alarm is silenced.
 - b. When the equipment item that is causing the alarm activation is identified, it will immediately be removed from service and tagged as "Do Not Use".
 - c. equipment removed from service will be cleared by the Biomedical Engineering department before returning to use.
- 3. In the event the LIM alarm remains activated after all equipment has been unplugged, the RN circulator will call Facilities Maintenance Department to have an electrician come to the OR.

Approved by:		Review/Revision Date:
		3/1993
		6/1996
<u>/s/</u>		1/1999
Michelle Mallett, MSN, RN, CNOR	Date	7/2002
Director Surgical Services		7/2005
•		6/10/2008
		9/2011
/s/		10/10/14
Kurt Kless, MSN, MBA, RN, NE-BC.	Date	2.1.2016
Chief Nursing Officer		8/1/2019
		12/31/2022
Review: Policy & Standard Committee, 9/11, 2/16, 8/19, 12/22		
Revision completed by: Greg Shannon, MSN, RN.		
		Next Review Date: 12/2025
Policies Superseded by This Policy: 4-24		